### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-004862

Address: 333 Burma Road **Date Inspected:** 01-Dec-2008

City: Oakland, CA 94607

**OSM Arrival Time:** 630 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes N/A No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component:** OBG

### **Summary of Items Observed:**

Caltrans Quality Assurance (QA) Inspector Tim McClendon arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China to periodically monitor welding and Quality Control (QC) functions. While on site the QA Inspector observed and/or discovered the following.

Bay 2 OBG Assembly Area - QA Observations:

This QA inspector performed Green Tagging of the following Deck Panels accompanied by ABF and ZPMC; the following items following Deck Panels were tagged on this date:

Panel number Tag number

DP432-001 2239

DP325-002 2231

DP460-001 2245

DP326-001 2240

DP461-001 2235

DP486-001 2286

DP298-001 2237

DP352-001 2234

DP406-001 2236

DP379-001 2246

DP407-001 2244

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

DP434-001 2247 DP351-001 2243 DP137-001 2241

# **Summary of Conversations:**

No relevant conversations spoken on this date.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Dautermann, Peter (707) 552-7715, who represents the Office of Structural Materials for your project.

Inspected By:	McClendon, Timothy	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer